

	A = 80	A = 100	A = 120	A = 140	A = 160	A = 180	A = 200	A = 220	A = 240	A = 260	A = 280	A = 300
B = 110	C = 938 C1 = 255 C2 = 50 D = 95°	C = 970 C1 = 285 C2 = 50 D = 105°	C = 997 C1 = 313 C2 = 50 D = 107°	C = 1.040 C1 = 357 C2 = 50 D = 114°	C = 1.084 C1 = 396 C2 = 50 D = 124°	C = 1.118 C1 = 429 C2 = 50 D = 125°	C = 1.122 C1 = 438 C2 = 50 D = 115°	C = 1.122 C1 = 438 C2 = 50 D = 108°	C = 1.118 C1 = 433 C2 = 50 D = 103°	C = 1.122 C1 = 438 C2 = 50 D = 97°	C = 1.120 C1 = 436 C2 = 50 D = 96°	C = 1.122 C1 = 438 C2 = 50 D = 90°
B = 130	C = 955 C1 = 273 C2 = 50 D = 95°	C = 985 C1 = 304 C2 = 50 D = 105°	C = 1.015 C1 = 331 C2 = 50 D = 105°	C = 1.048 C1 = 364 C2 = 50 D = 110°	C = 1.095 C1 = 412 C2 = 50 D = 120°	C = 1.118 C1 = 430 C2 = 50 D = 115°	C = 1.122 C1 = 438 C2 = 50 D = 110°	C = 1.122 C1 = 438 C2 = 50 D = 104°	C = 1.120 C1 = 434 C2 = 50 D = 98°	C = 1.118 C1 = 430 C2 = 50 D = 93°	C = 1.116 C1 = 431 C2 = 50 D = 92°	C = 1.122 C1 = 440 C2 = 50 D = 87°
B = 150	C = 975 C1 = 296 C2 = 50 D = 95°	C = 1.005 C1 = 324 C2 = 50 D = 102°	C = 1.032 C1 = 350 C2 = 50 D = 104°	C = 1.068 C1 = 385 C2 = 50 D = 110°	C = 1.110 C1 = 426 C2 = 50 D = 116°	C = 1.118 C1 = 434 C2 = 50 D = 109°	C = 1.120 C1 = 438 C2 = 50 D = 103°	C = 1.122 C1 = 439 C2 = 50 D = 98°	C = 1.118 C1 = 436 C2 = 50 D = 92°	C = 1.118 C1 = 430 C2 = 50 D = 90°	C = 1.122 C1 = 440 C2 = 50 D = 90°	
B = 170	C = 993 C1 = 316 C2 = 50 D = 95°	C = 1.022 C1 = 343 C2 = 50 D = 100°	C = 1.055 C1 = 371 C2 = 50 D = 104°	C = 1.088 C1 = 405 C2 = 50 D = 108°	C = 1.125 C1 = 440 C2 = 50 D = 114°	C = 1.118 C1 = 434 C2 = 50 D = 100°	C = 1.116 C1 = 435 C2 = 50 D = 97°	C = 1.105 C1 = 425 C2 = 50 D = 90°	C = 1.120 C1 = 440 C2 = 50 D = 90°	C = 1.120 C1 = 440 C2 = 50 D = 87°		
B = 190	C = 1.020 C1 = 345 C2 = 50 D = 93°	C = 1.045 C1 = 363 C2 = 50 D = 98°	C = 1.072 C1 = 392 C2 = 50 D = 103°	C = 1.105 C1 = 423 C2 = 50 D = 106°	C = 1.120 C1 = 438 C2 = 50 D = 102°	C = 1.122 C1 = 438 C2 = 50 D = 96°	C = 1.120 C1 = 438 C2 = 50 D = 92°	C = 1.116 C1 = 435 C2 = 50 D = 88°	C = 1.120 C1 = 440 C2 = 50 D = 86°			
B = 210	C = 1.035 C1 = 356 C2 = 50 D = 92°	C = 1.063 C1 = 383 C2 = 50 D = 97°	C = 1.087 C1 = 407 C2 = 50 D = 100°	C = 1.117 C1 = 437 C2 = 50 D = 101°	C = 1.120 C1 = 440 C2 = 50 D = 95°	C = 1.120 C1 = 440 C2 = 50 D = 90°	C = 1.122 C1 = 440 C2 = 50 D = 87°					
B = 230	C = 1.065 C1 = 390 C2 = 50 D = 92°	C = 1.085 C1 = 404 C2 = 50 D = 97°	C = 1.110 C1 = 428 C2 = 50 D = 98°	C = 1.119 C1 = 438 C2 = 50 D = 93°	C = 1.120 C1 = 440 C2 = 50 D = 88°	C = 1.120 C1 = 440 C2 = 50 D = 85°						
B = 250	C = 1.085 C1 = 407 C2 = 50 D = 92°	C = 1.102 C1 = 425 C2 = 50 D = 95°	C = 1.117 C1 = 437 C2 = 50 D = 92°	C = 1.120 C1 = 440 C2 = 50 D = 87°								
B = 270	C = 1.105 C1 = 433 C2 = 50 D = 91°	C = 1.110 C1 = 437 C2 = 50 D = 90°										

Montážní rozměry

